

General Environmental Incident Summary

Incident: 1959 **Date/Time Notice:** 6/26/2013 1620 **DEM Incident No:**

Responsible Party: Hatton Coop Oil

Date Incident: 6/26/2013 **Time Incident:** 0730 **Duration:**

County: Traill **Twp:** 148 **Rng:** 53 **Sec:** 18 **Qtr:**

Lat: 47.63598 **Long:** -97.46317 **Method:** Derived from TRS

Location Description: Hatton School, 503 4th St.

Submitted By: David Cameron

Affiliation:

Address:

City:

State:

Zip:

Received By: David Cameron

Contact Person: Scott Enger
603 Railroad Ave
Hatton, ND 58240

Distance Nearest Occupied Building: 0 Feet

Type of Incident: Tank Overflow

Description of Released Contaminant: #2 Fuel Oil

Volume Spilled: 700.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Cover was left off fill pipe. 4" rain last night filled 10,000 gal ust to overflowing. Tank is in courtyard so no overland runoff. Some seepage into School boiler room.

Risk Evaluation:

Risk is low as fuel has seeped into the soil.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

oil contaminated soil. no run-off because the site is surrounded by the school building.

Action Taken or Planned:

Water in tank will be removed and treated. David Cameron, NDDH will inspect soils to determine how much will need to be removed and landfarmed. Boiler room is being steam cleaned.

Wastes Disposal Location: unknown at this time

Agencies Involved:

Updates

Date: 7/7/2013

Status: Assigned to WM

Staff: Roberts, Kris

Updated Volume:

Notes:

Dave Cameron, WM, is following up.